Lower Owens River Project Flow Report for 04/19/2019

Augmenting Flow			Owens River Flows		
LORP Measuring Station	Daily	15 Day	Daily	,	# Days of
	Avg Flow(cfs)	Avg Flow(cfs)	Avg	Avg	last 15 at 40+ cfs
Polovy Divor Intole	Flow(CIS)	riow(cis)	<u> </u>	-	
Below River Intake			47	46	15
Blackrock Ditch Return (augmentation)	1	1			
Goose Lake Return (return flow)	0	0			
Billy Lake Return (augmentation)	1.4	1			
Mazourka Canyon Road			47	46	15
Locust Ditch Return (augmentation)	0	0			
Georges Ditch Return (augmentation)	0	0			
Reinhackle Springs			47	47	15
Alabama Gates Return (augmentation)	0	0			
At Pumpback Station ¹			48	49	15
Pump Station			44	45	
Langemann Gate to Delta			4	4	
Weir to Delta			0	0	
LORP In Channel Average Flow ²			47	47	

Pump Station Month-to-Date Average Flow 45 cfs

Blackrock Waterfowl Habitat Area

Flooded Unit	Area	Last Collected	Flow Rate	Flow Set Date		
Thibaut	19 Acres	01/23/2019	3.5 cfs	04/16/2019		
Winterton	100 Acres	01/23/2019	3.4 cfs	04/16/2019		
Drew	288 Acres	01/23/2019	3.7 cfs	04/16/2019		
Waggoner	0 Acres	05/31/2011	0 cfs	04/15/2011		
Total Flooded Area	407 Acres					
Off-River Lakes and	l Ponds					
Upper Twin Lake Gage Read		2.46 ft	(Last Colle	(Last Collected: 04/17/2019)		
Lower Twin Lake Gage Read		2.2 ft				
Goose Lake Gage R	ead	2.48 ft				
Thibaut Pond Flooded Area		28 Acre	S	(Last Collected: 01/23/2019)		

^{1.} Above Pump Station not constructed, the flow is the sum of the Pump station discharge, the Langemann Gate releases to the delta, and flow over the spillway weir to the delta.

^{2.} Average of the LORP Intake, Mazourka Canyon, Reinhackle Springs, and At Pumpback Station stations. Note - All Data shown in this report is from field electronic measuring and data collection devices.

Note - Data contained herein is preliminary and subject to change. Refer to the disclaimer: http://wsoweb.ladwp.com/Aqueduct/realtime/disclaimer.htm