Lower Owens River Project Flow Report for 06/18/2020

	Augmenting Flows		Owens River Flows		
LORP Measuring Station	Daily	15 Day	Daily	,	# Days of
	Avg Flow(cfs)	Avg Flow(cfs)	Avg Flow(cfs)	Avg) Flow(cfs	last 15 at 40+ cfs
Below River Intake			80	74	15
Blackrock Ditch Return (augmentation)	1	1			
Goose Lake Return (return flow)	0	0			
Billy Lake Return (augmentation)	1	1			
Mazourka Canyon Road			64	64	15
Locust Ditch Return (augmentation)	0	0			
Georges Ditch Return (augmentation)	0	0			
Reinhackle Springs			54	56	15
Alabama Gates Return (augmentation)	0	0			
At Pumpback Station ¹			43	46	15
Pump Station			40	43	
Langemann Gate to Delta			3	3	
Weir to Delta			0	0	
LORP In Channel Average Flow ²			60	60	

Pump Station Month-to-Date Average Flow 44 cfs

Blackrock Waterfowl Habitat Area

Flooded Unit	Area	Last Collected	Flow Rate	Flow Set Date	
Thibaut	0 Acres	05/12/2020	0 cfs	04/16/2020	
Winterton	191 Acres	05/19/2020	4.2 cfs	06/01/2020	
Drew	284 Acres	05/12/2020	4.3 cfs	06/01/2020	
Waggoner	0 Acres	05/31/2011	0 cfs	04/15/2011	
Total Flooded Area	475 Acres				
Off-River Lakes and	l Ponds				
Upper Twin Lake Gage Read		2.38 ft	(Last Collected: 06/17/2020)		
Lower Twin Lake Gage Read		2.21 ft			
Goose Lake Gage Read		2.48 ft			
Thibaut Pond Flooded Area (0 Acres	;	(Last Collected: 05/12/2020	

^{1.} Above Pump Station not constructed, the flow is the sum of the Pump station discharge, the Langemann Gate releases to the delta, and flow over the spillway weir to the delta.

^{2.} Average of the LORP Intake, Mazourka Canyon, Reinhackle Springs, and At Pumpback Station stations. Note - All Data shown in this report is from field electronic measuring and data collection devices.

Note - Data contained herein is preliminary and subject to change. Refer to the disclaimer: http://wsoweb.ladwp.com/Aqueduct/realtime/disclaimer.htm