LORP Measuring Station	Augment Daily Avg Flow(cfs)	ing Flows 15 Day Avg Flow(cfs)	Daily Avg	Avg	Flows # Days of last 15) at 40+ cfs
Below River Intake			81	78	15
Blackrock Ditch Return (augmentation)	1	1			
Goose Lake Return (return flow)	0	0			
Billy Lake Return (augmentation)	1	1			
Mazourka Canyon Road			69	66	15
Locust Ditch Return (augmentation)	0	0			
Georges Ditch Return (augmentation)	0	0			
Reinhackle Springs			56	55	15
Alabama Gates Return (augmentation)	0	0			
At Pumpback Station ¹			42	44	15
Pump Station			39	41	
Langemann Gate to Delta			3	3	
Weir to Delta			0	0	
LORP In Channel Average Flow ²			62	61	

Lower Owens River Project Flow Report for 06/23/2020

Pump Station Month-to-Date Average Flow 43 cfs

Blackrock Waterfowl Habitat Area

Flooded Unit	Area	Last Collected	Flow Rate	Flow Rate Flow Set Date		
Thibaut	0 Acres	05/12/2020	0 cfs	04/16/2020		
Winterton	191 Acres	05/19/2020	4.2 cfs	06/01/2020		
Drew	284 Acres	05/12/2020	4.3 cfs	06/01/2020		
Waggoner	0 Acres	05/31/2011	0 cfs	04/15/2011		
Total Flooded Area	475 Acres					
Off-River Lakes and Ponds						
Upper Twin Lake Gage Read 2.38 ft		(Last Colle	(Last Collected: 06/17/2020)			
Lower Twin Lake Gage Read		2.21 ft				
Goose Lake Gage Re	ead	2.48 ft				
Thibaut Pond Floode	d Area	0 Acres	3	(Last Collected: 05/12/2020)		

1. Above Pump Station not constructed, the flow is the sum of the Pump station discharge,

the Langemann Gate releases to the delta, and flow over the spillway weir to the delta.

2. Average of the LORP Intake, Mazourka Canyon, Reinhackle Springs, and At Pumpback Station stations. Note - All Data shown in this report is from field electronic measuring and data collection devices.

Note - Data contained herein is preliminary and subject to change. Refer to the disclaimer: http://wsoweb.ladwp.com/Aqueduct/realtime/disclaimer.htm